## **CONTRACTOR!**

Can you see a potential danger in your workplace? Do not wait - report!



Come up with remedial actions and you stand a chance of a prize!

#### Go through three steps:







to use a mobile phone at a place – Send a report!



3 Send a text message to 605 608 888. Provide the following: full name, name of company, location and description

Once every three months the board will choose the best three reports and their authors will get attractive awards!



I set high standards... and I care for others!

## List of hazardous substances at PKN ORLEN S.A. **Production Facility in Plock**

#### LIQUIFIED GAS (LPG)


























#### **HYDROGEN FLUORIDE - HF**


















C D E F G H I K L



entry with "S" pass only entry with permit only

evacuation gate

gate No 1 - main gate

gate No 2

gate No 5 4 gate No 10

5 gate No 21

6 Storage Depot in Plock







for personnel staying within the area of Polski Koncern Naftowy ORLEN S.A. **Production Facility in Plock** 

There are state and internal PKN's regulations included in Complex System of Prevention binding within the area of PKN ORLEN S.A. Production Facility in Plock

#### **Emergency telephone numbers:**



19 998



**Emergency telephone number** 

| 19 998       | Facility Rescue Phone (Fire Department) |
|--------------|---|
| 24 365 20 20 | Chief Dispatcher                        |
| 922          | OHS &Process Safety Department          |
| 24 365 44 99 | Environmental Inspection                |
| 24 365 33 33 | ORLEN Ochrona Ltd (Security)            |

Only valid magnetic entry ID card allows you to enter PKN ORLEN S.A. Production Facility in Plock.

Every person staying in the area of Production Facility is obliged to observe state and PKN's rules and standards.

### It is forbidden to: (for all personnel staying at PKN ORLEN S.A. Production Facility in Plock):

# All personnel staying at PKN ORLEN S.A. Production Facility in Plock is obliged to observe the following rules:

#### Chemical alarm:



move on roads other than main roads and drive exceeding the speed limit of 40 km/h,



drive in areas where an auxiliary permit or permit "S" is required.



smoke in areas other than those designated to do it,



use open fire without permission,



use mobile and trunk phones within production facility,



be under the influence of alcohol, carry in and consume alcoholic beverages, intoxicants and drugs,



carry in firearms, explosives and fireworks,





carry in cameras, video cameras, take pictures without a permit,



carry in empty jerry cans and containers for gasoline and other oil products.

- a) observe and obey HSE labels, warning signs and alarm signals,
- b) inform about any noticed HSE hazards calling the emergency phone number 19 998.
- c) use required personal protection means, i.e.:



protective helmet



protection goggles,



protective antistatic and flame retardant clothing,



protective antistatic footwear,



protective gloves selected to hazards.

#### Within areas where required to use:




hearing protection,



personal gas mask with an appropriate absorber – only during evacuation from the hazardous site,



non-sparkling tools and anti-explosive lighting fed from a 24 V transformer when executing works in a fire and explosion hazardous areas. Alarm announcement: modulated 3 min signal.



Alarm cancellation: continuous signal lasting 3 minutes.

3 min

#### **Emergency evacuation principles:**

- 1. take the gas mask.
- 2. determine wind direction.
- go to the evacuation assembly point / perpendicularly to the wind direction.

#### Methods of evacuation outside of the Production Facility in Plock:

- 1. roads: 7-8, A-B, E-F, F-G to exit gates,
- 2. gates: 1,2,5,10 and 21,
- 3. local roads in the direction to: Plock, Stara Biala, Trzepowo.